

## RW4 Plus / Ilco EZ<sup>®</sup>-Clone Plus Software Update *Version 02.00.056*

SW version 02.00.056 will allow the RW4 Plus and Ilco EZ Clone Plus devices to clone Philips (ID46) transponders when only one LED is illuminated on the Snoop. The Snoop LED is illuminated while at the vehicle. The majority of Philips (ID46) equipped vehicles continue to require 2 illuminated LED's on the Snoop to clone successfully. This software update allows the successful cloning of those vehicles that only provide one illuminated LED on the Snoop.

\*It is still recommended to turn the key in the ignition several times to attempt to receive 2 illuminated LED's on the Snoop. At this point, if only one LED is illuminated, please proceed with the cloning process with the RW4 Plus or EZ Clone Plus.

Some of the vehicles that have been noted to need only one Snoop acquisition are below. Consider that others may also work in the same way.

Make	Model	Make	Model
Acura	MDX	Dodge	Magnum
Chrysler	300	Fiat	500
Chrysler	PT Cruiser	Honda	Accord
Chrysler	Town & Country	Honda	CR-V
Dodge	Caravan	Honda	Insight
Dodge	Charger	Mitsubishi	Lancer
Dodge	Durango	Mitsubishi	Outlander

### How To Order:

This free update will be available on CD or by downloading from Ilco's FTP website (username and password protected). Ilco will provide user name and password when FTP link is sent.

To order, email the following information to [tech\\_support@irm.kaba.com](mailto:tech_support@irm.kaba.com):

Company Name  
Contact Name  
Address  
Valid email address  
Machine Type (RW4 Plus or Ilco EZ Clone Plus)  
Machine Serial Number

Please indicate if you prefer a CD mailed to you or the link to the Ilco FTP site emailed to you.

